

## ANNUAL VEHICLE INSPECTION REPORT

## VEHICLE HISTORY RECORD

REPORT  
NUMBER

FLEET UNIT NUMBER

948422

DATE

4-14-21

MOTOR CARRIER OPERATOR

ROY SALMON

INSPECTOR'S NAME (PRINT OR TYPE)

Chris Cooper

ADDRESS

9737 EUSTICE RD

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☐ YES

8441 F19 621655

CITY, STATE, ZIP CODE

RANDALLSTOWN MD 21033

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

3AK3G4D55F5G B9557

VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTION AGENCY LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKE SYSTEM</b>				<b>6. SAFE LOADING</b>				<b>10. TIRES</b>
✓			a. Service Brakes	✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	✓			a. Tires on any steering axle of a power unit.
✓			b. Parking Brake System	✓			b. Protection against shifting cargo.	✓			b. All other tires.
✓			c. Brake Drums or Rotors	✓			c. Container securement devices on intermodal equipment.	✓			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
✓			d. Brake Hose								
✓			e. Brake Tubing								
✓			f. Low Pressure Warning Device								
✓			g. Tractor Protection Valve								
✓			h. Air Compressor								
✓			i. Electric Brakes								
✓			j. Hydraulic Brakes								
✓			k. Vacuum Systems								
✓			l. Antilock Brake System								
✓			m. Automatic Brake Adjusters								
			<b>2. COUPLING DEVICES</b>				<b>7. STEERING MECHANISM</b>				<b>11. WHEELS AND RIMS</b>
✓			a. Fifth Wheels	✓			a. Steering Wheel Free Play	✓			a. Lock or Side Ring
✓			b. Pintle Hooks	✓			b. Steering Column	✓			b. Wheels and Rims
✓			c. Drawbar/Towbar Eye	✓			c. Front Axle Beam and All Steering Components Other Than Steering Column	✓			c. Fasteners
✓			d. Drawbar/Towbar Tongue	✓			d. Steering Gear Box	✓			d. Welds
✓			e. Safety Devices	✓			e. Pitman Arm	✓			
✓			f. Saddle-Mounts	✓			f. Power Steering	✓			
			<b>3. EXHAUST SYSTEM</b>				g. Ball and Socket Joints	✓			
✓			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	✓			h. Tie Rods and Drag Links	✓			
✓			b. Bus exhaust system leaking or discharging in violation of standard.	✓			i. Nuts	✓			
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓			j. Steering System	✓			
			<b>4. FUEL SYSTEM</b>				<b>8. SUSPENSION</b>				<b>12. WINDSHIELD GLAZING</b>
✓			a. Visible leak.	✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	✓			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
✓			b. Fuel tank filler cap missing.	✓			b. Spring Assembly	✓			
✓			c. Fuel tank securely attached.	✓			c. Torque, Radius or Tracking Components	✓			
			<b>4.114 LIGHTING DEVICES</b>				<b>9. FRAME</b>				<b>13. WINDSHIELD WIPERS</b>
✓			All lighting devices and reflectors required by Part 393 shall be operable.	✓			a. Frame Members	✓			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
							b. Tire and Wheel Clearance				<b>14. MOTORCOACH SEATS</b>
							c. Adjustable Axle Assemblies (Sliding Subframes)				Any passenger seat that is not securely fastened to the vehicle structure.
											<b>15. OTHER</b>
											List any other condition(s) which may prevent safe operation of this vehicle.
											R/F TURN CLEAR

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.